

SI-2-25-14-C


Replaces SI-2-25-14-B


KK-5044 EGA & EGHV Gun Repair Kit

Note

Old Style Fan Adjustment Assy.


When repairing the old style fan adjustment assembly (see inset), use two washers (Ref. No. 4) and one O-ring (Ref. No. 5). See parts explosion.





Fluid Tip & Gasket Note

Kit contains old and new style tip gaskets. Be sure to use the correct gasket according to the fluid tip. For additional identification, the thin gasket has a blue mark on edge.



| Ref. No. | Replacement Part No. | Description | Ind. Parts Req. |
|-------------|----------------------------|----------------------|-----------------------|
| 1 | EGA-59 | Gasket (new style) | 1 |
| | EGA-24 | Gasket (old style) | 1 |
| 2 | AG-3-1 | Trigger Bearing Stud | 1 |
| 3 | EGA-5 | Air Valve Plunger | 1 |
| 4 | AG-26 | Washer Kit (Brass) | 2 |
| 5 | SSG-8205 | O-Ring Kit | 1 |
| 6 | | Spring | 1 |
| 7 | AG-7 | Needle Spring | 1 |
| 8 | C-104 | Spring | 1 |
| 9 | SST-3008 | Ball | 1 |
| 10 | EGA-9 | Stem | 1 |
| 11 | 55-846 | Needle Packing | 1 |